DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001362 Address: 333 Burma Road **Date Inspected:** 27-Dec-2007

City: Oakland, CA 94607

OSM Arrival Time: 1300 **Project Name:** SAS Superstructure **OSM Departure Time:** 2330 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No N/A **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** N/A

Summary of Items Observed:

This Quality Assurance Inspector oversaw Quality Assurance Inspectors Paul Stovall, Scott Croff and Joe Lanz performing fabrication inspection out on the shop floor today.

Mr. Stovall performed magnetic particle testing on the root weld for the 89 Meter Mock-Up MUSB-MA29-10. Mr. Stovall also performed visual welding inspection on the 77 Meter mock-up MUA-MA1 E/F 15 skin A to diaphragm and the 89 Meter Mock-Up MUSB-MA25 splice plate. Mr. Lanz performed green tag releases on material to be sent to Wu Xi Boiler to be bent for bent flanges. Mr. Lanz also performed welding inspection in bay 7 on the OBG floor beams. Mr. Lanz reported on various floor beams having stiffeners tack welded in place or fillet welds being made between the stiffeners and floor beams. Mr. Croff performed visual and dimensional testing in bay 1 on the deck weld trial.

Summary of Conversations:

No conversations held today.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Berger,Bruce	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer